1 Products affected

Product hierarchy no. *			rchy no. *	Part no.	SBU	Type / D	Description	Customer part no.
SBU	PG	PUG	Туре				•	
01 00	002	022	0000000519	0031.8201 0031.8201.G	-Circuit protection	OGN	(22.5mm pin space)	n/a
	002	022		0031.8211 0031.8211.G		OGN	(25mm pin space)	n/a


*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

2 Type of change

- Modified label
- Improved electrical ratings
- Change of markings

3 Detailed description of change

The fuseholder OGN has new ratings and approvals as follow:



4 Reason of change

- Product improvement to fulfil the enhanced glow wire requirements according to the updated standard IEC 60127-6 and the standard IEC 60335-1 for appliances in unattended use.
- Recertification and rating enhancement by VDE
- Recertification and rating enhancement by UL

Product Change Notification						OGN new approval			
owner	creation date	release date	released by	change order no	rev	page	D10 007 255		
dislercy	2016-08-11	2017-01-31	nowakfr	2011797	A	1 of 2	D10-007-255		

5 Release date

The change will be rolled-out starting ww 23/2017 and lasts approx. 4 months.

6 Impact of change and recommended action

Form	Yes	Inscription on socket changed
Fit	No	No change for dimension
Function	Yes	Rating enhancement acc. IEC and UL/CSA
Manufacturing	No	No change for manufacturing site
Label	Yes	Approvals and configuration code on label
Packaging	No	No change in packaging

7 Reference Documents / Attachments

Kind of document	Remarks
Data sheet	

Product Change Notification						OGN new approval		
owner	creation date	release date	released by	change order no	rev	page	D10 007 055	
dislercy	2016-08-11	2017-01-31	nowakfr	2011797	А	2 of 2	D10-007-255	